

7.14.2015		09:30	Intersection of CR 8 & Malden Rd	
Meeting called by	Sam Pagli	a, EI, Drainage Superinte	endent	
Type of meeting	General C	Site Meeting: General Overview of Proposed Repair & Maintenance to the Colchester Townline Drain		
Facilitator	Sam Pagli	Sam Paglia, EI, Drainage Superintendent		
Note taker	Cheryl Cu	Cheryl Curran		
Attendees	Landowners:Gerry Santo, Roy Tayfel, Carmen Tayfel, Charley FaroughCounty of Essex:Dan Vujovic, Dan NewmanTecumseh:Sam Paglia, Cheryl Curran			
Background				
Discussion	Purpose o	Purpose of Meeting & Drainage Act Information		
		sediment and phragmites	rain banks are failing at several locations s are prohibiting water from draining nicated to the Drainage Superintendent	
efficiently. The drain by landowners. Mr. Paglia explained 1. To discuss t 2. To discuss t	age problem the purpose he bank failu he drain mai	sediment and phragmites s have also been commu e of the meeting: ares along the drain and the ntenance going forward;	s are prohibiting water from draining nicated to the Drainage Superintendent he required repair;	
efficiently. The drain by landowners. Mr. Paglia explained 1. To discuss t 2. To discuss t	age problem the purpose he bank failu he drain mai he process c	sediment and phragmites s have also been commu e of the meeting: ares along the drain and the ntenance going forward;	s are prohibiting water from draining nicated to the Drainage Superintendent he required repair; and	
efficiently. The drain by landowners. Mr. Paglia explained 1. To discuss t 2. To discuss t 3. To discuss t	age problem the purpose he bank failu he drain mai he process c	sediment and phragmites s have also been commu e of the meeting: ires along the drain and t ntenance going forward; a of repair and maintenance	s are prohibiting water from draining nicated to the Drainage Superintendent he required repair; and	

Following a review of the assessment apportionment by Crozier Baird Engineers at that time and concerns voiced by the affected landowners relating to the costs assessed to each landowner, it was found that a new assessment schedule was required to account for severances, zoning and use changes, inequities in the 1978 By-law and changes to drainage patterns in the Colchester Townline Drain.

Council adopted a new maintenance schedule of assessment for the Colchester Townline Drain on May 13th, 2014 under By-law 2014-14.



Section 74			
Discussion	Process		
process to complete the with the repair and mail andowners and Coun- were caused by the co The attendees asked w	with Process endance at the meeting held July 14, 2015 voiced their frustration with the ne drain maintenance. The landowners agreed that they were dissatisfied intenance work completed by Goodreau Excavating Ltd. in 2012. The ty of Essex representatives agreed that the bank failures occurring today ontractor undermining the banks of the drainage ditch during their 2012 work. why the Engineer was not on site during construction to ensure the quality of was done in accordance with the approved design.		
Sam could not speak to the amount of time the Project Engineer was on-site during Goodreau's work but did indicate to the attendees that the Engineer is normally not required to be on-site 100% of the time. The Engineer is to take notes, pictures and discuss any issues with the Contractor. All affected landowners are encouraged to walk the extent of the drainage works respecting their safety and report on any notable deficiencies to ensure the quality of work is acceptable.			
construction of a drain	<u>ction</u> 64 of the <i>Drainage Act</i> , any owner of land dissatisfied with the quality of the lage works at any time during construction or up to one year from the date of nage works may inform the Town of said concerns.		
was not taken at that t Superintendent follow concerns that they sta Goodreau to request t County of Essex have concerns to please for landowners then aske	ay's meeting stated that they did contact the Town with concerns but action time. The landowners questioned whether the previous Drainage ed the Act. Sam does not have a record of the landowners (and County) te were submitted within a year of the construction. Sam will meet with hey fixsome of the failures. Sam requests that if landowners and/or the a copy of any documentation sent to the Town at that time outlining their ward them to his attention to ensure it is filed within the Town's records. The d if the Town could claim this construction work under its insurance. Sam did a section within the Act that may provide financial assistance to the repair		
owing to any impro municipality or of a maintenance or re the referee or cou	tes the following: Where such damages and costs become payable oper action, neglect, default or omission on the part of the council of any any of its officers or employees in the construction, improvement, pair of the drainage works or in carrying out the provisions of this Act, rt may direct that the whole or any part of such damages and costs shall unicipality and be payable out of the general funds thereof.		
landowner side of the	d that according to the by-law, the work was to be completed from the drain, not the road side. Goodreau did not follow the engineer's Report and aintenance from the road side. This deviation from the by-law was approved		
repair of the drain. Sa benefiting landowners will be drafted asking agree to fix. Sam also	wners if the municipality's taxpayers could pay for the maintenance and am informed the attendees that any drainage work is to be assessed to the based on the adopted report and By-law 2014-14, but that a letter to Council for assistance for some of the failures if Goodreau Excavating Ltd. does not noted that if in fact, Goodreau fixes any of the failures, they will do so out of igation to the contract as the warranty period for this work has long elapsed.		



Bank Slopes

It was questioned by the landowners why the slopes of the drain bank are so steep. Sam indicated that while the standard bank slope should be no steeper than a 2:1 slope gradient (the ideal slope being 3:1), these ideal slope gradients cannot be achieved due to the close proximity of the municipal drain to the roadway shoulder and private property. The only way to construct the drain with 2:1 or 3:1 bank slopes is to relocate the drain away from the roadway and encroaching on private property.

It was pointed out at the meeting that 'someone' had placed stone along the banks of the drain from the 9th Concession Road westerly to just east of Walker Sideroad. Sam indicated that this work was done without authorization.

It was noted by one of the attendees that if the downstream ditches were maintained, this would facilitate the drainage of the Colchester Townline Drain. One of the landowners inquired if the Town could make one of the other landowners along a downstream drain submit a request for repair and maintenance. The Town cannot solicit requests, but has the responsibility to maintain and repair all municipal drains; the appointed engineer has a duty to provide that the downstream drain remains a sufficient outlet for the Colchester Townline Drain during the examination and report.

Required Repair & Maintenance Work

Sam inspected the drain earlier this summer (2015) and noted approximately 12 bank cave-ins along the length of the Colchester Townline Drain. Three additional issues were also brought to Sam's attention by abutting landowners.

The repair and maintenance work to the drain, currently requested by the County of Essex, would be completed under Section 74 of the *Drainage Act*. The current by-law for the drain, By-law 2014-14, will be used to recover costs. Assessments to all affected lands would follow the ratios set out and adopted in By-law 2014-14.

Sam further indicated that he cannot speak to what occurred prior to his employment with the Town nor the decisions made regarding this matter beyond what is documented in Town files. Sam requests the affected landowners together make a decision to:

- a) Expend their money and efforts in court to ascertain who is responsible for the existing cave-ins along the length of the drain and thus who is responsible for the cost to repair and maintain the drain; or
- b) Agree to repair the failing banks and maintain the drain to its original design; the total cost to be assessed to all affected landowners as set out in the assessment schedule. And, to further set a maintenance schedule going forward on a by-annual basis to maintain the condition and efficiency of the drain (i.e. remove phragmites, etc.).

Cost of Work

Discussion

Estimated Cost of Work & Assessment Schedule

Mr. Paglia explained the maintenance and repair work will be assessed to all benefiting landowners (including the County and Town of Tecumseh) according to the future maintenance schedule in Bylaw 2014-14.

Agricultural land abutting a municipal drain is assessed 2/3 cost to the landowner and 1/3 grant from OMAFRA (Section 85 (a) of the Act). No other costs (i.e. engineering; surveying) will be included in the repair and maintenance work.

Sam will not assess costs for work without first communicating with the affected landowners.



Contractors		
Discussion	Tender Submissions for Repair and Maintenance	
and maintenance. Sa Town's Procurement Sam noted that many	ers request a list of all contractors that are able to perform the required repair am will provide a Contractor List of estimates for the work based on the Policy. small contractors do not submit quotes for drain work, as some are not ork; some do not have the required insurance or the required bond.	
Meeting Adjournment & Contact Information		
Meeting adjourned at 10:30 a.m. Should any of the attendees wish to discuss the drain maintenance work further, please contact:		
Sam Paglia, El, Drainage Superintendent Town of Tecumseh 519-735-2184 ext. 105		