




South Wall of the Main Lesperance Pumping Station. Wet Well Damaged.

CHIPPEWA PARK

RIVERSIDE DR.

LESPERANCE RD



LESPERANCE ROAD STORM PUMPING STATION

Riverside Drive @ Lesperance Road

Car Accident Damage March 6, 2023



March 6, 2023
Tecumseh G.I.S